ENDANGERED SPECIES OBSERVER PROGRAM SEA TURTLE INCIDENTAL TAKE DATA FORM

Project Name: Long BOAT Koy Beach 18	Perour. USACE District: JACKSONV. 11e
Dredge Name: Bayport	Dredge Firm: MANSON
DATE: 1.25-06 Time turtle take reco	overed (24hr): 1900 Turtle take # for project:
LOAD'#: 543 Times (24brs): Star	rt 1706 End 1857 Load start date 1.25-06
	rhead Green Kemp's ridley Hawksbill Leatherback
Channel location of take: Latitude 27 32 Other location / Channel description (e.g. buoy mar	Longitude 8246.5 kers, landmarks): Nobth T.P ANNA MARIA ISLAN
Location take recovered on dredge: STARBOA	RD Front Screen
Number of dragheads in use at time of incident: 2 Condition of deflector: good	Draghead deflector? YES X NO
	5 6 7 8 9 10 11 12
AIR TEMP: 67 °C/® (°F = 9/5 (°C) +3 WATER TEMP: Surface 63 °C/® Column (2; °C = 5/9 (°F - 32)) (mid-depth) °C /°F Bottom °C /°F
	Flippers recovered. Appeared Frogh #1
0 - Allyay Espain dood 2 - Moderately despect	
	= Severely decomposed; 4 = skeleton/old bone; 5 = undetermined Age class: Juy Sub-Adult Adult UN
Measurements: Circle units	Head Width:cm/in
Plastron Length: cm/in	Plastron Width: cm/in
Carapace Straight Length:cm/in	Carapace Straight Width: cm/in
Carapace Curved Length: cm/in Measurement/description of part:	Carapace Curved Width:cm/in
Genetic samples taken: YESNO	Photos taken: YES NO
Turtle tagged?: YES NO X Tag ty Final disposition of specimen:	pe: Tag #: Tag date:
Comments:	
Load data form attached: YES X NO	Dredge load log attached: YESNO
Observer's name Robert DUNCAN COASTWISE CONSULTING	
Use diagrams below to illustrate specimen/part recov	vered:

and a

BAYPORT Sea Turtle Incidental Take Report

25 Jan 06

While dredging in borrow area 9, load # 543, remains of a sea turtle were found in the Stbd forward lander screen. The head, front flippers, and a small segment of shell were recovered. The turtle appeared to be freshly killed. Robert Duncan, the turtle observer on board notified me of the take, and I witnessed it's removal from the lander, no other parts of the turtle were found. In my opinion this turtle was taken after the pumps were clutched out, and the impeller was spinning down. The draghead was lifted off the bottom at the conclusion of the load and the turtle was taken. The carcass had no sand in it, and was small enough that it was barely caught in the 4" by 4" screening on the lander. Had the pump been

clutched in the force of water would have forced the remains through

William D. Anderson Master, Dredge Bayport

the screen.